| Approved_For Rele | ease 2004/05/12 : CIA-RDP63- 99 31 | 3A000500140133-5 |
|--|--|--|
| | | Copy _// |
| | | 8 November 1963 |
| | | |
| MEMORANDUM FOR: | Assistant Director, OSA Deputy Assistant Director, | OSA |
| SUBJECT : | Summary of OSA Activities 2 November 1963 | for Week Ending |
| OXCART | | |
| inlet control which was aircraft was flown at a 72,000 feet with this c fying. Other tests will time this control is pla | trol: Lockheed has designed installed on Aircraft #127 for maximum speed of Mach 2. ontrol installed. Initial result be run to confirm the initial anned as a backup to the Hamified in the current OXCART | for test purposes. The 62 and an altitude of ults of this test were gratical findings. At the present cilton-Standard inlet con- |
| fin have been accomplied present inventory of fine The first of | stic Fins: Static tests of a new lished with successful results ins is being modified to the new fins was installed lown at the end of this report | e. Consequently, the new configuration at ed on Aircraft #130. The |
| was turned over to our | aft: The second J58 powered redetachment The ration reported as satisfactor | he article has been flown |
| IDEALIST | | |
| | | |

25X1

25X1

25X1

25X1

| 2. Triple Prime Over Cu | ba: Aircraft #342 | 2 flew three BRASS KN | ЮВ |
|---|---|---|---------------|
| een returned to the base at E ent to ITEK for inspection an riple Prime camera is now k | Triple Prime candwards. The cand danalysis of its o | mera. The aircraft hatera has been removed perational condition | ts now and |
| btain four double convergent nticipated in four to six mont | stereo camera sy | stems with first delive | ry |
| | | | |
| | | | 25 |
| | | | |
| | | | |
| ATELLITES | | | |
| | | | 2 |
| 2. ARGON Mission 9059A October. The payload was: November at 1939 EST. The | recovered success | sfully by air snatch on | |
| ENERAL | | | |
| | | | |
| | | | |
| | | | |

25X1

| C | C | 1 | 7 | 7 |
|---|---|---|---|---|
| Ü | | | | Ï |

25X1

25X1

25X1

| 3EGKE I | | |
|---------|--|--|
| | | |
| | | |
| | | |

- 4. MURAL Camera Damage: MURAL camera #26 was damaged during a test, due to an error in powerline routing, and has been returned to ITEK for inspection and repair. This camera is the backup for the second MURAL flight. The impact of the damage on the satellite schedule is being evaluated. No flight slippage is anticipated based on available information concerning the malfunction.
- 5. Satellite Control Programmers: A meeting was held to discuss obtaining additional programmers in support of NRO programs. OSA Personnel Branch is making a survey to determine the implications of this requirement. It will make positive recommendations as to whether or not these additional people can be supplied from a CIA ceiling or whether they must be supplied from an Air Force roster. A final decision on this matter will be made based on the background factors known to higher management. In the meantime, support is being offered through interim actions covered by Security and temporary staffing.
- Aircraft: Based on the approaching operational date of the OXCART program, the Director, NRO, was requested to transfer the aircraft to the OXCART program. This was three uncommitted done for several reasons, the most obvious of which are: (a) one aircraft is needed to replace the OXCART #123 which was lost during early development; and (b) the supply and maintenance program will be simplified by consolidating all similar aircraft under single management. Expeditious consideration and an affirmative response were requested.
- 7. NRO Briefing Material: A series of charts concerning the OXCART program has been completed by the OSA Operations Division. This briefing material was shown to Dr. Wheelon in a dry run and pronounced acceptable with a few minor changes. It is now ready to be given to Dr. McMillan at his convenience.

Chief, Programs Staff

